

RECORD OF THE MISCELLANEOUS EVENTS OF THE DAY

0000 - 0700

0000 Checked all vis A/N.
 0200 Checked all vis A/N.

F. Guyette

0400 Checked all vis A/N. 0400 - 0800

0600 Checked all vis A/N. Extinguished stations Main Light.
 0710 Held revellie.

M A Heath

0800 - 1200

0800 Held morning colors. Turned to on stations work.

0810 Heath SA departed station on 48 hr. liberty in C.G. 16585

0815 Started sta. eng. gen. and put same on line for test

0830 Took 7.0. and 7.0. soundings.

0850 Hardone BM-1 arrived this station in C.G. 16585 from 48

~~0850~~ Guyette departed for castle hill 4/BSTA. with CG-16585

1130. Seared from work.

1135 Guyette EN3. RETURN TO STA.

J H Hardone.

1200 - 1600

1200- Dinner.

1300- Turn in

1330 Seared from work

W Macdonald

1600 - 2000

1600. Checked all vis A/N.

1700- Evening show.

1755- Turn on main light

1810- Evening show

1900- checked all vis A/N.

1930- checked boat

2000 - 2400

2000- checked all vis A/N

2300- checked all vis A/N

2330 checked boat.

F. Guyette

J H Hardone

CERTIFIED TO BE CORRECT

[Signature]
 (Officer in Charge)

RECORD OF THE MISCELLANEOUS EVENTS OF THE DAY

0000-0400

0000. Checked all rig A/r.

0300. checked boat

W. Ladomirsky

0400-0800

0400. checked all rig A/r.

0430. Turn on fog sig.

0700. Held Buell's

F. G. Grette

0800-1000

0800. morning colors. Turn in.

0830 Secured stations fog signals & Main Light.

1130. Secured from work.

1135. Drill. FIRE

1145. Secured from drill

J. H. Hardone

1200-1600

1200. Dinner.

1300 Turn in station work

1400 Secured from work.

F. G. Grette

1600-2000

1600 Checked all rig A/r CG-16585 departed for CH/ONS

1658 CG 16585 returned station

1730 Turn on main light
Secured repairing and satisfactorily testing stations
P-50 fire pump.

1900. Checked all rig A/r.

1910. checked boat

2000-2400

W. Ladomirsky

2000. checked all rig A/r.

2200. checked boat

J. H. Hardone.

CERTIFIED TO BE CORRECT

J. H. Hardone
(Officer in Charge)

RECORD OF THE MISCELLANEOUS EVENTS OF THE DAY

0000- checked all vis 4/r.
0100- checked boat.

0000- 0400

F. Hengette

0400- 0800

0400- checked all vis 4/r.
0600- Secured main light.
0700- Evening colors.

W. Godomski

0800- 1200

0800- morning colors, Turn To.
0830- Godomski RA. Departed on liberty on CG-16585
0930 Heath SA returned from 48hr. liberty in CG-16585
1110 Hardone cut his hand departed with Heath as Corporal in C.G. 16585.
1130 Secured from work
1135 Mail

J. H. Hardone

1200- 1600

1200- Dinner.
1230. Hardone BU, return from Naval Newport Hospital.
1300- Turn To.
1555- Secured from work.

RA Heath

1600- 2000

1600- checked boat,
1730- Evening chow.
1757- Turn on main light.
1812- Evening colors
1813- North light extinguished- Report to castle Hill.
1840- North light back in operation
2000- 2400

F. Hengette

2000- checked all vis 4/r.

2200- checked boat.

2200- Put in

2215- Rec P 040302Z. SCW displayed J. Hardone

CERTIFIED TO BE CORRECT

J. H. Hardone BU
(Officer in Charge)

RECORD OF THE MISCELLANEOUS EVENTS OF THE DAY

0000-0400

0000- Check A/r. Vis Poor.
 0010- checked boat.

M A Heath

0400-0800

0400- Vis, Poor.

0600- checked boat.
 0700- Held. Buil.

F. Hingette

0800-1200

0800- morning colors. Turn to
 0900- Secured fog sig. and main light
 1025- REL. DO 4145PZ
 1130- Secured from work.
 1135- Dred

J H Sardone

1200-1600

1200- Dinner
 1300- Turn to.
 1545- Secured from work

RA Heath

1600-2000

1600- checked all vis A/r.
 1700- Evening show.
 1757 Turn on main light.
 1813 Evening colors
 1915 checked boat and scene.

F. Hingette

2000-2400

2000- checked all vis A/r
 2200- checked boat.
 1025- Rec. O- O. 50315Z
 1045- Bring boat way up on beach.
 1110- Rec. O- O. 5034PZ

J H Sardone

CERTIFIED TO BE CORRECT

J H Sardone
 (Officer in Charge)

RECORD OF THE MISCELLANEOUS EVENTS OF THE DAY

0000 - checked all in a/n.
0200 - checked boat.

0000 - 0400

R. A. Heath

0400 - checked all in A/A
0500 - checked boat.

0400 - 0800

0600 - Secured main light
0700 - Held Buell

0800 - 1200

F. Luyette

0800 - morning colors Turn to.
1130 - Secured from work.
1135 - Drill
1145 - Secured from drill

J. R. Sordone

1200 - 1600

1400 - Dinner
1500 - Turn to
1520 - REC. P 051922Z
1530 - Secured from work
1530 SEND P 051930Z.

R. A. Heath

1600 - 2000.

1600 - checked all in a/n.
1700 - Evening chow.
1800 - checked boat.
1800 - Turn on main light
1815 - Evening colors.

F. Luyette

2000 - checked all in a/n.
2100 - checked boat.
2130 - REC. P 060202Z
2300 - checked boat

J. R. Sordone

CERTIFIED TO BE CORRECT

J. R. Sordone

(Officer in Charge)

RECORD OF THE MISCELLANEOUS EVENTS OF THE DAY

0000 - 0400

0000 checked all ris $\frac{1}{2}$
 0010 checked front.

RA Heath

0400 - 0800

0400 checked all ris $\frac{1}{2}$
 0550 Secured main light
 0730 Held Arlie

T. Luyotte

0800 - 1200

0800 morning close field day.
 0900. Luyotte departed on liberty
 0915 Godonick's return from liberty
 1135 Secured from inspection of station

J. H. Harlowe

1200 - 1600

1200 Dinner.
 1500 no food.

RA Heath

1600 - 2000

1600 - checked all ris $\frac{1}{2}$
 1700 - Evening show.
 1800 - Turn on main light.
 1815 - Evening colds.
 1900 - checked front.

W. Harlowe

2000 - 2400

2000 checked ris $\frac{1}{2}$
 2155 Rec P 070240Z.
 2300 checked front.

J. H. Harlowe

CERTIFIED TO BE CORRECT

J. H. Harlowe B41
 (Officer in Charge)

RECORD OF THE MISCELLANEOUS EVENTS OF THE DAY

0000-0400

0000- checked all rig's
0012 - checked boat.

RA Heath

0400-0800

0400- checked all rig's
0600- Seared main light

J K Stardone

0800-1200

0800- morning colors
1100- checked all rig's
1130- vis good.
1135- checked boat.

W Stardone

1200-1600

1200- Dinner
1300- checked boat

RA Heath

1600-2000

1600- checked all rig's
1800- Turn on main light
1815- Evening colors
1900- checked boat.

W Stardone

2000-2400

2000 checked all in 4-
2122 Rec P080206Z
2300 checked boat.

J K Stardone

CERTIFIED TO BE CORRECT

J K Stardone
(Officer in Charge)

RECORD OF THE MISCELLANEOUS EVENTS OF THE DAY

0000- Checked all vis R/N
 0010- Secured boat.

0000-0400

R. U. Heath

0400-0800.

0400- checked all vis, R/N, and boat.
 0600- Secured main light.
 0700- Held. Anchor

W. Hubbard

0800-1200

0800- morning colors. Turn in,
 1130- Secured from watch
 1135- Drill
 1150- Secured from drill

J. R. Sordone

1200-1600

1200. Dinner.

1205 Nordone departed on 48 hr liberty
 1300 Guyette EN-3 returned from liberty. R. U. Heath
 1500 Checked all vis R/N.

1600-2000

1600 checked all vis R/N.
 1630 Secured for the day.
 1800 Displayed main light.
 1815 Held evening colors.

W. Hubbard

2000-2400

2000 checked all vis R/N
 2215 Rec P O 90234Z

F. Guyette

CERTIFIED TO BE CORRECT

Floyd Guyette EN-3
 (Officer in Charge)

RECORD OF THE MISCELLANEOUS EVENTS OF THE DAY

0000 - 0400

0000 Checked all vis #/N.
 0200 Checked all vis #/N. Checked boat.
 RA Heath

0400 - 0800

0400 Checked all vis #/N.
 0600 Extinguished Main light.
 0710 Held revellie.
 W. Huchins

0800 - 1200

0800 Held morning colors, Turned to,
 1000 Checked all vis #/N.
 1130 Secured for chow.
 1135 Dull
 1150 Secured from dull
 F. Hayette

1200 - 1600

1200 Checked all vis #/N, checked boat.
 1300 Turned to. Held fire drill.
 1400 Checked all vis #/N.
 RA Heath

1600 - 2000

1600 Checked all vis #/N.
 1630 Secured for the day
 1800 Displayed stations M. Light.
 1815 Held evening colors,
 W. Madams

2000 - 2400

2000 Checked all vis #/N. Checked boat.
 2200 Checked all vis #/N
 2300 Checked boat

F. Hayette

CERTIFIED TO BE CORRECT

F. Hayette EN-3
 (Officer in Charge)

RECORD OF THE MISCELLANEOUS EVENTS OF THE DAY

0000 - 0400

0000 Checked all vis A/W.

0200 Checked all vis A/W. Checked load,

F. Guyette

0400 - 0800

0400 checked all vis A/W

0600 Rec P 1009302

0700 turned main light

0730 Revell

R A Heath

0800 - 1200

0800 Morning Colors,

0910 turned to station work.

1010 Heath Sx departed station on 48 hr. liberty,

1050 Hardone BM1 arrived station from liberty,

1100 Started Stations emg. gen. for test runs.

1130 Secured for chow.

1135 Drill

1150- Secured from drill

F. Guyette

1200 - 1600

1200 DINNER

1300- Turn to

1535- Secured from work

J H Hardone

1400 - 2000.

1400- vis good.

1730- Evening meal.

1800- Turn on main light

1820- Evening color

1900- checked all vis apr.

V. A. Selenski

2000 - 2400

2000- checked all vis A/W

F. Guyette

CERTIFIED TO BE CORRECT

J B Hardone BM1
(Officer in Charge)

RECORD OF THE MISCELLANEOUS EVENTS OF THE DAY

0000-0100

0000- checked all vis A/R.
 0010- checked boat.

J R Gardone

0400-0800

0400- checked all vis A/R.
 0405- checked boat.
 0600- Secured main light
 0700- Held. Anlie

F. Hugette

0800-1200

0800- Morning colors. Turn to.
 1130- Secured from work.
 1135- Drill
 1150- Secured from drill

1200-1600

W. McDermott

1200- Dinner.
 1300- Turn to.
 1550- Secured from work

J R Gardone

1600-2000

1600- vis good.
 1630- Secured for the day. checked boat.
 1700- Evening down.
~~1800- Check~~ 1800- Displayed stations main light.
 1810- Held evening colors.

F. Hugette

2000-2400

2000 Checked stations - small boat
 2200 Checked all vis A/R.

W. McDermott

CERTIFIED TO BE CORRECT

J R Gardone B.M.
 (Officer in Charge)

RECORD OF THE MISCELLANEOUS EVENTS OF THE DAY

0000 - 0400

0000 Checked all vis #/N. Checked stations boat.
 0200 Checked all vis #/N.

F. Luyette

0400 - 0800

0400 Checked all vis #/N.
 0500 Rec. P-1207 042/03 J R Mardone
 0600 Secured main light.
 0700 Held Builil

0800 - 1200

0800 - Morning colors. Turn to.
 1100 - Godomuske F.A. departed on USM, liberty
 1130 - Heath returned from 48 hr liberty
 1136 - Secured from work F. Luyette

1200 - 1600

1200 Checked all vis #/N.
 1300 Turned to.
 1555 - Secured from work. B A Heath

1600 - 2000

1600 - checked all vis #/N.
 1605 - Rec. P 1220 542
 1730 - Evening chow.
 1806 - Turn on main light J R Mardone
 1822 - Evening colors.

2000 - 2400

2000 - checked all vis #/N.
 2200 Checked all vis #/N. Checked boat.
 F. Luyette

CERTIFIED TO BE CORRECT

J R Mardone
 (Officer in Charge)

RECORD OF THE MISCELLANEOUS EVENTS OF THE DAY

0000 - 0400

0000 Checked all via A/N

0200 Checked all via A/N.

F. Huxette

0400 - 0800

0400 - Checked all via A/N. Checked boat.

0600 - Secured main light.

0730 - Held. Arrived

J. B. Haddon

0800 - 1200

0800 - morning colors.

0805 - field day.

1130. Secured from field day

RA Heath

1200 - 1600

1200 Dinner.

1600 - checked boat on morning

F. Huxette

1600 - 2000

1600 - checked all via A/N.

1700 - Evening meals.

1800 - checked boat.

J. B. Haddon

2000 - 2400

2000 - checked all via A/N

2005 - checked boat.

2300 - checked boat

F. Huxette

CERTIFIED TO BE CORRECT

J. B. Haddon
(Officer in Charge)

RECORD OF THE MISCELLANEOUS EVENTS OF THE DAY

0000-0400.

0000- checked all ris Apr.

0010- checked boat.

0400-0800

F. Luyette

0400- checked all ris Apr.

0600- second light- checked boat.

J. H. Marlowe

0800-1200

0800- morning colors.

0900- Luyette E-3 departed on liberty

RA Heath

1000- Edomish F.A. Return from liberty

1200-1400.

1200- Dinner.

1500- checked all ris Apr.

W. Edomish

1600-2000.

1600- checked boat.

1700- Evening show.

1800- Turn on main light

1824- Evening colors

2000-2400

J. B. Marlowe

2000- checked all ris Apr.

2100- checked boat.

RA Heath

CERTIFIED TO BE CORRECT

J. B. Marlowe
(Officer in Charge)

RECORD OF THE MISCELLANEOUS EVENTS OF THE DAY

0000- checked all A/R of
0010- checked boat.

0000-0400

0400-0800

W. Adamshu

0400 checked all rigging and boat.
0600- secured main light
0700- Held. Aulic

J. R. Hardone

0800-1200

0800- Morning colors Jun 20.

1000- C.G. Spar arrived with water Rec. 9,000 gal
of water.

1100- C.G. 65 arrived to delivered 50 gal. of gasoline

1130- completed Seaflag inspection

R. U. Heath

1200 1400

1200- Dinner.

1230- C.G. SPAR. DEPARTE UNIT.

1300- Jun 20

1350- Secured from work

1555- Held safety meeting

W. Adamshu

1600-2000

1600- Checked all rig A/R.

1700- Evening chow

1809- Jun on main light

1826 Evening colors

R. U. Heath

2000-2400

2000- checked all rig A/R.

2100- checked boat.

J. R. Hardone

CERTIFIED TO BE CORRECT

J. R. Hardone

(Officer in Charge)

RECORD OF THE MISCELLANEOUS EVENTS OF THE DAY

0000. 0400

0000 - checked all vis A/N
 0010 - checked front.

RA Heath

0400 - 0900

0400 - checked all vis A/N.
 0600 - secured main light.

0700 - Held Purtil
 0730 - Mardone departed on light
 0800 - 1200

J. A. Mardone

0900 - morning colors. Turn to
 0810 - Guynette SW-3 returned from liberty.
 0930 - turned to station work.
 1130 - secured for noon chow.

1200 - 1600

J. Guynette

1200 - checked all vis A/N.
 1300 - resumed work.

W. Shadomisho

1600 - 2000

1600 - checked all vis A/N
 1615 - resumed work.
 1800 - Displayed main light
 1820 - evening color.

RA Heath

2000 - 2400

2000 - checked all vis A/N.
 2200 - Checked all vis A/N. Checked boat J. Guynette

CERTIFIED TO BE CORRECT

Delayed Guynette on 3
 (Officer in Charge)

RECORD OF THE MISCELLANEOUS EVENTS OF THE DAY

0000 - 0400

0000 checked all vis #1
 0100 checked boat.
 0445 Received P/1808302 from SEA

0400 - 0800

W. Haden

0400 checked all vis #1
 0600 secured main light
 0630 Radio
 0700 turned to station work.

PA Heath

0800 - 1200

0800 checked all vis #1 Morning colors
 0810 Turned to station work and outside of building,
 1000 checked all vis #1/N.
 1130 Secured for chow.
 1135 Drill

F. H. Myette

1200 - 1600

1200 checked all vis #1/N. Checked boat.
 1300 Turned to.
 1500 checked all vis #1/N.
 1600 Checked boat.

PA Heath

1600 - 2000

1630 Secured for the day.
 1700 Chow.
 1800 Displayed Main Light.
 1830 Held evening colors.
 1830 Checked all vis #1/N.

W. Haden

2000 - 2400

2000 checked boat and all vis #1/N.
 2200 checked all vis #1/N.

F. H. Myette

CERTIFIED TO BE CORRECT

Floyd H. Myette
 (Officer in Charge)

RECORD OF THE MISCELLANEOUS EVENTS OF THE DAY

0000 - 0400

0000 Checked all vis H/W.
 0200 Checked all vis H/W. Checked boat & sta.

0400 - 0800

W. Madenke

0400 Checked all vis H/W.

0600 Secured main light

0630 Runkle

0715 turned to stolon work

RA Heath

0740 Placed fog signal in operation

0800 - 1200

0800 Morning colors. Turn to

0805 Fog.

0809 Heath SS departed on liberty with CG. 16580.

0930 - Madone Bu return from liberty

1130. Secured from work

J H Madone

1135. Drill fire

1155. Secured from drill

1200 - 1600

1200. Dinner.

1300. Turn to.

1555. Secured from work.

T. Hays

1600 - 2000

1600. checked all vis H/W.

1700. Evening colors.

1815. Turn on main light

1829. Evening colors

W Madenke

2000 - 2400

2000 Checked all vis H/W

2030 Received P/1907842 lower SCW

2300. checked boat.

J H Madone

CERTIFIED TO BE CORRECT

J H Madone
 (Officer in Charge)

RECORD OF THE MISCELLANEOUS EVENTS OF THE DAY

0000 - 0400

0000 - checked all in A/P.
 0010 - checked front.

F. Hargette

0400 - 0800

0400 - checked all in A/P.
 0600 - secured main light.
 0700 - Held Berke.

W. Ladomuski

0800 - 1200.

0800 - Morning colds. Turn on
 1130 - Secured from work.
 1135 - Drill
 1145 - Secured from drill

J. R. Sardon

1200 - 1600

1200 - Dinner
 1300 - Turn on
 1335 - Secured from work

F. Hargette

1600 - 2000

1600 - checked all in A/P.
 1700 - Evening meal.
 1815 - Turn on main light.
 1830 - Evening colds.
 1910 - Rec. 1922 44Z

W. Ladomuski

2000 - 2400

2000 - checked all in A/P.
 2345 - Should say sig & call the bell

J. R. Sardon

CERTIFIED TO BE CORRECT

J. R. Sardon
 (Officer in Charge)

RECORD OF THE MISCELLANEOUS EVENTS OF THE DAY

0000 - checked all is A/R
 0000 - checked boat.

0000 - 0400

F. Luyette

0400 - in pool

0400 - 0800

0700 - Held Ruhl

J. R. Malone

0800 - 1200

0800 - morning colts.

0815 - Turn to field day.

0830 - Jedomski departed on 2 day liberty

0900 - Secured from inspection

0930 - Heath returned from liberty

1030 - Turned to painting exterior of building.

1130 - Secured from inspection.

R. A. Heath

1200 - 1600

1200 - Dinner.

1300 - checked boat

F. Luyette

1600 - 2000.

1600 - checked all is A/R.

1800 - Evening chow

1815 - Turn on main light

1831 - Evening colts

2000 - 2400.

J. R. Malone

2000 - checked all is A/R.

2200 - checked boat.

1816 - Turn on main light.

1832 - Evening colts.

R. A. Heath

CERTIFIED TO BE CORRECT

J. R. Malone

(Officer in Charge)

RECORD OF THE MISCELLANEOUS EVENTS OF THE DAY

0000 - 0400

0000 checked all vis F/W.

0200 Checked all vis F/W. Checked boat

0400 checked all in the

0600 secured main light

0630 Rumble

J H Gardner
J Guyette

0800 - 1200

0800 Mowing weeds.

1000 checked boat.

R A Heath

1200 - 1600

1200 - Dinner.

1500 - checked boat

J H Gardner

1600 - 2000

1600 - checked all vis A/R

1700 - Evening meal.

1900 - checked boat

2000 - 2400

J Guyette

2000 - checked all vis A/R.

2300 - checked boat.

R A Heath

CERTIFIED TO BE CORRECT

J H Gardner
(Officer in Charge)

RECORD OF THE MISCELLANEOUS EVENTS OF THE DAY

0000-0400

0000 - checked all vis Apr.

0100 - checked boat.

J K Hardoe

0400-0800

0400 - checked all vis Apr.

0600 - Turn off main light.

0700 Held Patrol

J Guette

0800-1200

0800 Morning colors.

0815 Tended to station work.

1130 - Secured from work.

1135 - Drill

M Heath

1200-1600.

1200 - Dinner.

1230 - Guette departed on 2 day liberty.

1240 - Godoniske return from liberty.

1300 - Turn to.

1555 - Secured from work.

J K Hardoe

1600-2000

1600 - checked all vis Apr.

1700 - Evening chow.

1817 - Turn on main light.

1832 - Evening colors.

C Edwards

2000-2400.

2000 - checked all vis Apr.

2300 - checked boat.

M Heath

CERTIFIED TO BE CORRECT

J K Hardoe B.N. 1
(Officer in Charge)

RECORD OF THE MISCELLANEOUS EVENTS OF THE DAY

0000-0400.

0000- checked all vis Apr.
0010- checked boat.

W. Radonke

0400-0800

0400. checked all vis Apr.
0600- secured main light.
0700- Held Amulit

J A Harlowe

0800-1200

0800- Morning colors Turn To.
1130- secured from work.
1135- Drill fire

RA Heath

1200-1600

1200- Dinner.
1300- Turn To-
1530- secured from work.

W. Radonke

1600-2000.

1600- checked all vis Apr.
1830- Turn on main light.
1834- Evening colors
1900- Evening meals
1930- checked boat. 2000-2400

J A Harlowe

2000 checked all vis Apr.
2200- checked boat.

RA Heath

CERTIFIED TO BE CORRECT

J A Harlowe 341
(Officer in Charge)

RECORD OF THE MISCELLANEOUS EVENTS OF THE DAY

0000-0400

0000- checked all vis. A/N.

0010- checked boat.

W. H. Hordonshe

0400-0800

0400- checked all vis. A/N.

0600- Secured light

0700- Held Ruelie

J. H. Hordonshe

0800-1200

RA Heath

0800- morning work. Turner

1015- CG 40522 arrived unit with district safety inspector

1100- CG-40522. departed station with A.S. SACTH KAR. DIST. SAFETY INSPECTOR.

J. H. Hordonshe

1200 - 1600

1200 Checked all vis. A/N.

1210 Nardone BM-1 departed on liberty.

1225 Annette CN-3 returned from 48 hr. Liberty.

1235 Heath SA departed star. to bring storm window into be fixed.

1320 Heath SA. returned.

1530 checked all vis. A/N. checked boat.

Y. Annette

1600 - 2000

1600 checked all vis. A/N.

1630 Secured for the day.

1820 Displaid main light

1830 Held evening colors.

1930 checked all vis. A/N.

RA Heath

2000 - 2400

2000 checked all vis. A/N.

2200 checked all vis. A/N. checked boat.

2300 Made routine check of station grounds

Y. Annette

CERTIFIED TO BE CORRECT

Y. Annette EN-3
(Officer in Charge)

RECORD OF THE MISCELLANEOUS EVENTS OF THE DAY

0000 - 0400

0000 Checked all vis #/N.

0200 Checked all vis #/N. Checked, [unclear]

0400 - 0800 W. Holinski

0400 checked all vis #/N.

0600 Secured main light

RA Heath

0630 Revellin

0715 turned to station work.

0800 - 1200

0800 Morning colors. Turned to,

1000 Checked all vis #/N.

1130 Secured floor show.

J. Huxette

1200 Checked all vis #/N.

1300 Turned to

1330 Heath departed station to pick up windows

1405 Heath returned station

1600 - 2000 W. Holinski

1600 checked all vis #/N.

1615 Secured for the door & Rec P 252320Z

1830 Unplugged main light.

1935 Evening colors.

RA Heath

2000 - 2400

2000 checked all vis #/N.

2043 Reported to Coast Hill that Bull

Kicks now extinguished.

2145 - Rec P 260234Z.

W. Holinski

CERTIFIED TO BE CORRECT

J. Huxette

(Officer in Charge)

RECORD OF THE MISCELLANEOUS EVENTS OF THE DAY

0000 - 0400

0000 Checked all vis ^{am}
 0200 checked all vis ^{PM}. Checked boat.

0400 - 0800

W. Haddock

0400 Checked all vis ^{pm}
 0600 Checked all vis ^{PM}. Secured main light.
 0700 Held revellie.
 0800 Held morning ^{0800 0007. Huggins} colors. Turned to
 1000 Checked all vis ^{PM}.
 1110 Heath SH departed station on 48 hr. liberty.
 1125 Haddone arrived station from liberty.
 1130 Secured for chow

1200 - 1600

W. Haddock

1200 checked all vis ^{PM}.
 1300 Turned to stations work.
 1555 - Secured from work.

J. H. Haddock

1600 - 2000

1600 checked all vis ^{PM}.
 1700 Evening chow.
 1705. At 262140Z
 1737 Turn on main light.
 1738 - Evening colors.
 1900. checked boat.

2000 - 2400

F. Huggins

2000 - checked all vis ^{PM}.
 2300 - checked boat.

J. H. Haddock

CERTIFIED TO BE CORRECT

J. H. Haddock
 (Officer in Charge)

RECORD OF THE MISCELLANEOUS EVENTS OF THE DAY

0000-0400

0000 - checked all vis A/n.
0010 - checked boat.

F. Luyette

0400-0800

0400 - checked all vis A/n.
0700 - Held Radio

W. Lacombe

0800-1200

0800 morning colors
0800 - Turn to field day.
1130 - Secured from inspection

J. H. Malone

1200-1600

1200 - Dinner.
1500 - checked all vis A/n.

F. Luyette

1600-2000

1600 - checked boat.
1700 - Evening meals
1828 - Turn on main light.
1830 - Evening colors.

W. Lacombe

2000-2400

2000 - checked all vis A/n.
2100 - checked boat

J. H. Malone

CERTIFIED TO BE CORRECT

J. H. Malone
(Officer in Charge)

RECORD OF THE MISCELLANEOUS EVENTS OF THE DAY

0000 - 0400

0000 - checked all rig 4/12

0010 - checked boat.

0400 - 0800.

Floyd Hengette

0400 - checked all rig 4/12

0600. Second main light.

0800 - 1200

J. H. Arlone

0800 - morning colors.

0800 - Godomuske. SA departed on 2 days liberty.

0845 - Heath SA returned from liberty

1130 - checked boat.

BA Heath

1200 - 1600

1200 - Dinner.

1530 - checked boat.

F. Hengette

1600 - 2000

1600 - checked all rig 4/12.

1700 - Evening meals.

1925 - Turn on main light

1940 - Evening colors

F. Hengette

2000 - checked all rig 4/12

2300 - checked boat.

J. H. Arlone

CERTIFIED TO BE CORRECT

J. H. Arlone
(Officer in Charge)

RECORD OF THE MISCELLANEOUS EVENTS OF THE DAY

0000-0400

0000- checked all air A/R.

0010- checked boat.

RA Heath

0400-0800

0400- checked all air A/R.

0600- Secured main light.

0700- Held backie

F. G. Myette

0800-1200

0800- Morning colors.

0900- Turn on.

1135- Secured from work.

1135- Drill fire

1150- Secured from drill

J. R. Harbison

1200-1600

1200- Dinner.

1300- Turn on.

1535- Secured from work.

RA Heath

1600-2000

1600- checked all air A/R.

1700- Evening colors.

1925- Turn on main light.

1941- Evening colors.

F. G. Myette

2000-2400-

2000- checked all air A/R.

0235 Rec 030156Z.

J. R. Harbison.

CERTIFIED TO BE CORRECT

J. R. Harbison B. M.
(Officer in Charge)

RECORD OF THE MISCELLANEOUS EVENTS OF THE DAY

0000-0400

0000- checked all rig a/r.

0010- checked frst.

0200- checked boat.

F. G. Geyette

0400-0800

0400- checked all rig a/r.

0600- Secured main light.

0700- Held. Anchor

R. A. Heath

0800-1200

0800- morning colors

0810- Turn in.

0900- Geyette departed on 48 hr. liberty.

1030- Goddard's F.A. Return from liberty J. H. Gardner

1130- Secured from work.

1145- checked boat OK

1200-1600

1200- checked all rig a/r.

1215 Rec 3016002.

1245 Lt 40522 arrived unit with Mr. Campagna
and Commander. Cheney.

1300- checked boat OK

1400- checked boat OK

1450- Commander. Cheney. and Group commander departed
station

1550- Secured from work.

✓ W. L. Adams

1600-2000.

1600- checked all rig a/r.

1730- Turn on main light.

1900- Evening colors.

R. A. Heath

2000-2400

2000- checked all rig a/r.

2300- Placed fog signals in operation J. H. Gardner.

CERTIFIED TO BE CORRECT

J. H. Gardner
(Officer in Charge)